1 PREPARATION

1 PACKAGE CONTAINS:

☐VG-35MAIN FRAME
☐AC CORD ☐VG-35 MANUAL CD-ROM
☐DATA MANAGER INSTALLER CD-ROM
☐ CALIBRATION CERT. ☐QUICK START GUIDE ☐DOUBLE-FACED ADHESIVE TAPE

OPTIONAL ITEMS

☐CHART RECORDER (WITH CABLE)
☐USB CABLE ☐COMPACT FLASH MEMORY

2 SETTING

SET THE MACHINE ON FLAT PLACE.
DURING MEASUREMENT, SLIDER PROTRUDES TO THE LEFT. SO, MAKE ENOUGH OPEN SPACE IN THE LEFT SIDE OF THE MACHINE

3 POWER ON

TURN ON THE POWER SWITCH AT THE BACK OF THE UNIT.

4 CARRIER TAPE SETTING

PASTE THE DOUBE-FACED ADHESIVE TAPE ON THE SLIDER AND FIX THE EMBOSSED TAPE ON IT

5 FIX COVER TAPE TO CLIP



POINT !

PUT THE COVER TAPE THRU HOLE AND CLOSE MAGNET FLAP AND CLIP.



MOVE THE SLIDER FORWARD BY HAND AND MAKE COVER TAPE PEELING ANGLE

6 ADJUSTMENT OF LOADCELL HEIGHT

LOADCELL HEIGHT ADJUSTMENT KNOB



ROTATE THE ADJUSTMENT KNOB UNTIL THE CLIP COMES TO NEAREST LEVEL TO THE COVER TAPE

2 MEASUREMENT

1 START THE MEASUREMENT



WHEN PREPARATION IS FINSIHED, PRESS START SWITCH AND START MEASUREMENT

2 AT MEASUREMENT

DURING MEASUREMENT, DATA WILL BE DISPLAYED ON THE SCREEN

3 FINISH OF MEASUREMENT

MEASUREMENT WILL FINISH WHEN STOP/REV BUTTON IS PRESSED OR 、SLIDER MOVES UP TO THE LIMITED POSITION。

4 MEASUREMENT DATA



PEEL BACK FORCE TESTER VG-35 QUICK START GUIDE 2

VG35QS003

Vanguard SYSTEMS INC.

3 MEASUREMENT DATE SAVING

1 PROCESS OF DATA SAVING



AFTER MEASUREMENT, PRESS SAVE BUTTON。
REPLY THE CONFIRMING MESSAGE ON DISPLAY。

2 SELECTION OF DATA SAVE SITE／INPUT OF FILE



SELECT DATA SAVING SITE FROM 01～16 BY SCROLLING WITH ∧∨BUTTON AND DECIDE WITH ENT BUTTON. UP TO 16 FILES CAN BE SAVED.



SELECT LETTER WITH< >BUTTON AND PRESS ENT. MAX. 16 LETTERS CAN BE INPUT. AFTER INPUT OF FILE NAME, MOVE < > TO OK POSITION AND PRESS ENT BUTTON TO FINISH.

4 DATA MANAGER INSTALLMENT

1 SWITCH ON YOUR PC AND CONNECT TO VG35 WITH USB CABLE, THEN, HARDWARE WIZARD WILL START UP.

2 INSERT『VG35 DATA MANAGER INSTALLER CD-ROM』AND PROCEED ACCORDING TO THE DISPLAYED PROCESS.

3 OPEN『VG-35 Setuo』IN CD ROM



4 SETUP WIZARD WILL START UP

5 DATA MANAGER START UP

1 START UP…

DOUBLE CLICK SHORTCUT WILL BE MADE ON DISK.

Data Manager will start up

2 VARIOUS DATA INPUT

INPUT NECESSARY ITEMS。(NO INPUT IS OK)

3 TRAMSFER OF DATA VIA USB

3-1 CONNECT VG-35 TO YOUR PC WITH USB CABLE (AB (Mini) TYPE.

CONNECT USB CABLE AB (Mini) TYPE (OPTION) TO UBS SOCKET

3-2 PRESS TRANSFER BUTTON AND SELECT USB ON DISPLAY



Vanguard SYSTEMS INC.

3-3 DATA MANAGER データ取得 IS TO BE CLICKED

IF YOU HEAR "BEEP"SOUND FROM VG-35 MAIN UNIT, TRANSFER HAS BEEN FINISHED.

4 DATA TRANSFER WITH COMPACT FLASH

4-1 INSERT COMPACT FLASH TO VG-35

INSERT COMPACT FLASH TO THE CF SOCKET AT SIDE OF VG-35.

4-2 PRESS TRANSFER ON PEEL BACK FORCE DISPLAY AND SELECT CF CARD.



4-3 INPUT FILE NAME AND SAVE IT IN COMPACT FLASH



MAXIMUM 8 LETTERS

FILE FORM IS CSV

IF YOU HEAR "BEEP" SOUND FROM VG-35, SAVING HAS FINISHED

4-3 AFTER SAVING, TAKE OUT COMPACT FLASH FROM VG-35 AND INSERT IT TO PC.

4-4 DATA MANAGER データファイルを開く IS TO BE CLICKED

4-3 SELECT COMPACT FLASH IN WHICH FILE IS SAVED AND CLICK TO OPEN.

CLICK

5 STARTUP EXCEL

5-1 TRANSFER VIA UBS, OR READ OUT DATA FROM COMPACT FLASH AND CLICK エクセル実行

5-2 PEEL BACK FORCE REPORT WILL OPEN. METHOD OF PRINTING AND SAVING IS SAME AS OPERATION OF NORMAL EXCEL